


Photo Album for City of Waukesha Fire Department, WI Job 35796 July 23, 2021

In this report your cab completed paint while the forward body module was not available, and the body continued fabrication. In the next report your cab may begin assembly, the forward body module may be available, and the body may complete fabrication.



DSC04726



DSC04727



DSC04728



DSC04729



DSC04730



DSC00172



DSC00173



DSC00174



DSC00175



DSC00176



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956