Photo Album for Fennimore Fire Dept., WI Job # 35950 W/O # 27293370 August 7, 2021


This week the cab began to receive trim and wiring harnesses and the chassis frame began initial assembly. The pump house began the paint process, and the body was in staging. Next week the cab should continue to receive trim and wiring harnesses and the chassis frame should continue with assembly. The pump house may finish with paint and the body should begin to receive trim and wiring harnesses.



DSC00244



DSC00246



DSC00245




DSC00247





DSC00248



DSC00250



DSC00249



DSC00251



DSC00252



DSC00284



DSC00253



DSC00285





DSC00286



DSC00288



DSC00287



DSC00289





http://reliantfire.com/



An Oshkosh Corporation Company



