




Photo Album for Bristol Fire Department, WI Job F7413 September 17, 2021

In this report your cab and chassis are staged while your body completed the paint process. In your next report, assembly of your apparatus may continue while the body may be merged.

Your next scheduled report from Weyauwega is the week ending October 01, 2021.



DSC09059



DSC09060



DSC09061



DSC09062



DSC09063



DSC09064



DSC09065



DSC09066



DSC09067



DSC09068



DSC09069



DSC09070



DSC09071



DSC09072



DSC09073



DSC09074



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

