
The background of the slide features a collage of fire-related images. On the left, a firefighter in a white helmet and jacket is shown. In the center, a fire truck is visible with the words 'FIRE-RESCUE' on its side. On the right, there is a large fire with thick white smoke rising from it. At the bottom, several firefighters in yellow gear are working on a fire scene.

Photo Album for Ames, IA Job 36258 December 17, 2021

In this report your cab started assembly while the torque box is staged, and the body started fabrication. In your next report the cab may begin initial assembly while the torque box is staged, and the body continues fabrication.

Due to limited staffing and production during the upcoming Christmas and New Year's weeks, your next report on this unit is scheduled for week ending January 8, 2022.

Thank you for your business – Wishing you all the best of the Holiday Season!



DSC04605



DSC04606



DSC04607



DSC04608



DSC04609



DSC04473



DSC04474



DSC04475



DSC00215



DSC00216



DSC00217



DSC00218



DSC00219



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956