




Photo Album for Raymond Fire & Rescue, WI Job 36172 December 17, 2021

In this report the cab started assembly while the pump house is staged, and the body completed paint and initial assembly. In your next report the cab may continue assembly while the pump house and body are staged.

Due to limited staffing and production during the upcoming Christmas and New Year's weeks, your next report on this unit is scheduled for week ending January 8, 2022.

Thank you for your business – Wishing you all the best of the Holiday Season!



DSC04540



DSC04541



DSC04542



DSC04543



DSC04544



DSC04455



DSC04456



DSC04457



DSC04392



DSC04393



DSC04394



DSC04395



DSC04396



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956