

# Photo Album for Clermont, IA

Job # 36175

W/O # 27418179

January 29, 2022

This week the chassis arrived and began the paint process, the pump house structure was joined with the fire pump and the body continued the paint process. Next week the chassis may finish with paint, and the pump house could begin the paint process. The body should finish with paint.



DSC00190



DSC00191



DSC00192



DSC00193





DSC00194



DSC00195



DSC00196



DSC00197





DSC00198



DSC00199



DSC00200



DSC00257





DSC00258



DSC00259



DSC00260



DSC00261





DSC00262



DSC00457



DSC00458



DSC00459



DSC00460



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

© 2005-2022 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956