Photo Album for West Des Moines Fire Department, IA Job 36203 January 28, 2022

In this report your tractor cab remained staged, the pump house is staged, the three body modules completed the paint process, the tiller cab is staged, the aerial device sections remain staged, and the trailer is not available for photos. In your next report the tractor cab, the pump house, the body modules, and aerial device may remain staged. The trailer was not available for photos. In your next report the cab, the pump house, the body modules, the tiller cab, and aerial device may remain staged.





DSC04844





DSC04846 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956









DSC04817







DSC04819 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC01177





DSC01179 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC01181





DSC01183 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC04725





DSC04727 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC04729





DSC01172 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



f





DSC01174







DSC00087 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956









http://reliantfire.com/



An Oshkosh Corporation Company



©2005- 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956

