
Photo Album for Clermont, IA Job # 36175 W/O # 27418179 February 19, 2022

This week the chassis continued with chassis prep and the pump house was mounted. The body was in staging. Next week the body should be mounted.



DSC00366



DSC00368



DSC00367



DSC00369





DSC00370



DSC00372



DSC00371



DSC00373





DSC00374



DSC00376



DSC00375



DSC00377





http://reliantfire.com/



An Oshkosh Corporation Company



