Photo Album for West Des Moines Fire Department, IA Job 36203 February 04, 2022

In this report your tractor cab remained staged, the pump house is staged, the three body modules completed the paint process, the tiller cab is staged, the aerial device sections remain staged, and the trailer is not available for photos. In your next report the tractor cab, the pump house, the body modules, and aerial device may remain staged. In your next report the cab, the pump house, the body modules, the tiller cab, and aerial device may remain staged.





DSC05177





DSC05179 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956










DSC05180



DSC05119



DSC05121 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956





DSC01011





DSC01013 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC01015





DSC01017 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956











DSC01021 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC01023





DSC01025 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC01027





DSC01029 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956









http://reliantfire.com/



An Oshkosh Corporation Company



©2005- 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956

