

Photo Album for Castalia FD, IA

Job # 36363

W/O # 27514289

March 5, 2022

This week the chassis was in staging (no photos), and the pump house structure was joined with the fire pump. The body began the paint process. Next week the chassis should be in staging, and the pump house may begin the paint process. The body should continue with paint.




DSC00435



DSC00436



DSC00437



DSC00438



DSC00439



DSC00497



DSC00498



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956