
Photo Album for Castalia FD, IA Job # 36363 W/O # 27514289 March 26, 2022

This week the chassis began preparations for fire service, and the pump house was in staging. The body was unavailable for photos. Next week the chassis should continue with chassis prep and the pump house may be mounted.



DSC00391



DSC00393



DSC00392



DSC00394



DSC00395



DSC00397



DSC00396



DSC00398





DSC00399



DSC00401



DSC00400





http://reliantfire.com/



An Oshkosh Corporation Company



