


Photo Album for Cottage Grove Fire Department, WI Job 36398 March 25, 2022


In this report your cab was merged with the frame, the pump house completed paint, and the body continued in paint. In your next report the chassis may continue assembly, the pump house may continue assembly, and the body may continue in paint.



DSC05229



DSC05230




DSC05231



DSC05232



DSC05233




DSC05234



DSC05235



DSC05236



DSC05237



DSC05238



DSC05239



DSC05240




DSC05241



DSC05242



DSC05243



DSC05275



DSC05276



DSC05277



DSC05212



DSC05213



DSC05214



DSC05215



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956