



Photo Album for
Ixonía FD., WI
Job # 36381
W/O # 27514452
March 5, 2022

This week the chassis was in staging (no photos), and the pump house structure was joined with the fire pump. The body finished the paint process. Next week the chassis should be in staging, and the pump house may begin the paint process. The body may begin to receive trim and wiring harnesses.



DSC00005



DSC00006



DSC00007



DSC00008



DSC00009



DSC00010



DSC00266



DSC00267



DSC00268



DSC00269



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956