



Photo Album for
Ixonía FD., WI
Job # 36381
W/O # 27514452
March 12, 2022

This week the chassis was in paint, and the pump house was in staging. The body began to receive trim and wiring harnesses. Next week the chassis may finish with paint, and the pump house may begin the paint process. The body may continue with trim and wiring harnesses.



DSC00081



DSC00082



DSC00083



DSC00084



DSC00085



DSC00086



DSC00087



DSC00088



DSC00165



DSC00166



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956