



Photo Album for McFarland Fire and Rescue, WI Job 36382 March 11, 2022

In this report your cab continued through paint and the body started fabrication. In your next report the cab may continue the paint process and the body may continue fabrication.





DSC04580



DSC04581




DSC04582



DSC04583



DSC04584



DSC00127



DSC00128



DSC00129



DSC00130



DSC00131



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956