


Photo Album for McFarland Fire and Rescue, WI Job 36382 March 18, 2022

In this report your cab continued through paint, the body continued fabrication, and the aerial device sections have arrived. In your next report the cab may continue the paint process, the body may continue fabrication with release to paint, and the aerial device will remain staged with no photos until assembly begins.



DSC05059



DSC05060




DSC05061



DSC05062



DSC05063




DSC04660



DSC04661



DSC04662



DSC00039



DSC00040



DSC00041



DSC00042



DSC00043



DSC00377



DSC00378



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

