


Photo Album for West Des Moines Fire Department, IA

Job 36203

March 04, 2022

In this report the body modules continued assembly and the tiller cab was installed. The aerial device remained staged with no photos. In your next report apparatus assembly may continue while the aerial device may remain staged.



DSC01000



DSC01001



DSC01002



DSC01003



DSC01004



DSC01005



DSC01006



DSC01007



DSC01008



DSC01009



DSC01010



DSC01011



DSC01012



DSC01013



DSC01014



DSC01015




DSC01016




DSC01017



DSC01018



DSC01019



DSC01020



DSC01021




DSC01022




DSC01023



DSC01024




DSC01025



DSC01026



DSC01027



DSC01028



DSC01029




DSC01030



DSC01031



DSC01032




DSC01033



DSC01034



DSC01035



DSC01036



DSC01037



DSC01038



DSC01039




DSC01040




DSC01041



DSC01042



DSC01043



DSC01044



DSC01045



DSC01046



DSC01047



DSC01048



DSC01049



DSC01050



DSC01051



DSC01052



DSC01053



DSC01054



DSC01055



DSC01056



DSC01057



DSC01058



DSC01059



DSC01060



DSC01061



DSC01062



DSC01063



DSC01064



DSC01065



DSC01066



DSC01067



DSC01068



DSC01069



DSC01070



DSC01071



DSC01072



DSC01073



DSC01074



DSC01075



DSC01076



DSC01077



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956

