
Photo Album for Castalia FD, IA Job # 36363 W/O # 27514289 April 2, 2022

This week the chassis continued with chassis prep, and the pump house was in staging. The body began to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the pump house could be mounted and may be the body.



DSC00420



DSC00422



DSC00421



DSC00423





DSC00424



DSC00426



DSC00425



DSC00440





DSC00441



DSC00443



DSC00442



DSC00444





DSC00445





http://reliantfire.com/



An Oshkosh Corporation Company



