



Photo Album for
Castalia FD, IA
Job # 36363
W/O # 27514289
April 9, 2022

This week the chassis continued with chassis prep, and the pump house mounted. The body was in staging. Next week the chassis should continue with chassis prep and the body should be mounted.



DSC00340



DSC00341



DSC00342



DSC00343



DSC00344



DSC00345



DSC00346



DSC00347



DSC00348



DSC00392



DSC00393



DSC00394



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956