## Photo Album for Cottage Grove Fire Department, WI Job 36398 April 01, 2022

In this report your chassis continued assembly, the red is being sprayed on the pump house, and the body completed initial assembly. In your next report the chassis may continue assembly, the pump house may complete the paint process, and the body may be staged.



DSC04897



DSC04899



DSC04898



DSC04900





DSC04901



DSC04903



DSC04902



DSC04904





DSC04905



DSC04907



DSC04906



DSC00038





DSC00039



DSC04414



DSC00040



DSC04415





DSC04416



DSC04418



DSC04417





http://reliantfire.com/



An Oshkosh Corporation Company



