



Photo Album for
Barnum, IA
Job # 36676
W/O # 27776600
July 2, 2022

Since the last report, the chassis began preparations for fire service and the pump house structure was joined with the fire pump. The body began the paint process. Next week the chassis should continue with chassis prep and the pump house may begin the paint process. The body may finish with paint.



DSC00452



DSC00453



DSC00454



DSC00455



DSC00456



DSC00457



DSC00458



DSC00459



DSC00460



DSC00649



DSC00650



DSC00651



DSC00652



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956