



Photo Album for
Barnum, IA
Job # 36676
W/O # 27776600
July 9, 2022

This week the chassis continued with chassis prep and the pump house began the paint process. The body also continued the paint process. Next week the chassis should continue with chassis prep and the pump house should finish with paint. The body may finish with paint.



DSC00373



DSC00374



DSC00375



DSC00376



DSC00377



DSC00568



DSC00569



DSC00570



DSC00571



DSC00572



DSC00573



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956