
Photo Album for Barnum, IA Job # 36676 W/O # 27776600 July 16, 2022

This week the chassis continued with chassis prep and the pump house began final pump assembly. The body began to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the pump house may be mounted. The body should continue with trim and wiring harnesses.



Find us on Facebook

f









DSC00343



© 2005-2022 Fire & Safety Consulting, LLC





DSC00347















DSC00350




DSC00351










DSC00425









DSC00429



DSC00430









DSC00433











http://reliantfire.com/



An Oshkosh Corporation Company



