

Photo Album for
Barnum, IA
Job # 36676
W/O # 27776600
July 23, 2022

This week the chassis continued with chassis prep and the pump house was in test. The body was in staging.


Next week the chassis should continue with chassis prep and the pump house could be mounted and may be the body.



DSC00572



DSC00573



DSC00574



DSC00575



DSC00576



DSC00577



DSC00578



DSC00579



DSC00580



DSC00581



DSC00582



DSC00583



DSC00584



DSC00585



DSC00586



DSC00587



DSC00592



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956