Photo Album for Sullivan Fire Department, WI Job 36878 September 09, 2022

In this report the cab continued initial assembly while the frame build continued, and the body started in paint. In the next report the cab may continue initial assembly while the frame build may continue, and the body may continue in the paint process.






DSC04925





DSC04927 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



f





DSC01687





© 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



DSC01688









DSC01691



DSC01693 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



36878-01



DSC07176







DSC07178 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956









DSC04608



DSC04610 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



DSC04609





DSC04612





http://reliantfire.com/



An Oshkosh Corporation Company



©2005- 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956

