Photo Album for Sullivan Fire Department, WI Job 36878 September 30, 2022

In this report chassis assembly continued, the pump house started paint, and the body continued initial assembly. In the next report the chassis may continue assembly, the pump house may continue in paint, and the body may be staged.



DSC05339



DSC05341



DSC05340



DSC05342





DSC05343



DSC05345



DSC05344



DSC05346





DSC05347



DSC05349



DSC05348



DSC05350





DSC05351



DSC05353



DSC05352



DSC05354





DSC05355



DSC05357



DSC05356



DSC07071





DSC07072



DSC07074



DSC07073



DSC07075





DSC05168



DSC05170



DSC05169



DSC05171





DSC05172





http://reliantfire.com/



An Oshkosh Corporation Company



