
## Photo Album for Council Bluffs, IA Job 38453 October 21, 2022

In this report your cab completed paint and started initial assembly, the frame build continued, your pump house completed assembly and was staged, and your body was staged to continue the paint process. In the next report your cab may continue initial assembly, the frame build may continue, your pump house may remain staged, and your body may continue through paint.





DSC05326






DSC05328 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



DSC05327

Find us on Facebook









DSC05329

DSC05210



© 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956





DSC05214





DSC05216 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



DSC05215









DSC06064 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956









DSC06066



DSC01018



DSC01019 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956









DSC05259





© 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956





DSC05263





http://reliantfire.com/



An Oshkosh Corporation Company



©2005- 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956

