




Photo Album for Council Bluffs, IA Job 38453 October 28, 2022

In this report the cab and pump house were installed on the chassis, the front body is staged, and the rear body continued in paint. In the next report chassis assembly may continue while the front body is staged, and the rear body continues in paint.



DSC01453



DSC01454



DSC01455



DSC01456



DSC01457




DSC01458



DSC01459



DSC01460



DSC01461



DSC01462



DSC01463



DSC01464



DSC01465




DSC01466



DSC01467



DSC01468



DSC01469



DSC01470



DSC01471



DSC01472



DSC01473



DSC01474



DSC01475



DSC01476



DSC01477



DSC01478



DSC01479



DSC01480



DSC01481




DSC01482




DSC01483




DSC01484



DSC01485



DSC01486



DSC01487



DSC01488



DSC01489



DSC00051



DSC00052



DSC00053



DSC04638



DSC04639



DSC04640



DSC04641



DSC04642



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2022 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956