



# Photo Album for Council Bluffs, IA Job 38453 November 11, 2022

In this report chassis assembly continued, and the body modules are staged for initial assembly. In the next report the torque box may be installed on the chassis while the body modules remain staged for initial assembly.



DSC07145



DSC07146



DSC07147



DSC07148





DSC07149



DSC00013



DSC00014



DSC01093



DSC01094



DSC01095



DSC01096



DSC01097



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2022 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956