



Photo Album for
Thornton IA.
Job # 37287
W/O # 30222743
December 3, 2022

Since the last report, the chassis continued with chassis prep and the pump house structure was joined with the fire pump. The body was unavailable for photos. Next week the chassis should continue with chassis prep and the pump house may begin the paint process.



DSC00142



DSC00143



DSC00144



DSC00145



DSC00146



DSC00147



DSC00148



DSC00149



DSC00150



DSC00151