




Photo Album for
Thornton IA.
Job # 37287
W/O # 30222743
December 17, 2022

This week the chassis continued with chassis prep and the pump house began the paint process. The body began to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the pump house should begin final pump assembly. The body may finish with trim and wiring harnesses.



DSC00300



DSC00301



DSC00302



DSC00303



DSC00304



DSC00305



DSC00306



DSC00307



DSC00308



DSC00309



DSC00310



DSC00311