



Photo Album for
Thornton IA.
Job # 37287
W/O # 30222743
December 24, 2022

This week the chassis continued with chassis prep and the pump house began final pump assembly. The body continued to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the pump house may be mounted along with the body.




DSC00233



DSC00234



DSC00235



DSC00236



DSC00237



DSC00238



DSC00239



DSC00240



DSC00330



DSC00331



DSC00332



DSC00333



DSC00334



DSC00335



DSC00336



DSC00337



DSC00338



DSC00339



DSC00340