Photo Album for Lake Prairie Twp. Fire Dept., IA Job # 37220 W/O # 30187496 January 7, 2023

Since the last report, the chassis continued with chassis prep and the pump house was unavailable for photos. The body continued the paint process. Next week the chassis should continue with chassis prep and the body should finish with paint.



DSC00173



DSC00174





DSC00176



DSC00175



DSC00177



DSC00178





DSC00287



DSC00286



DSC00288

