

**Photo Album for
Thornton IA.
Job # 37287
W/O # 30222743
January 7, 2023**

Since the last report, The chassis continued with chassis prep and the pump house was mounted. The body was unavailable for photos. Next week the body should be mounted.




DSC00233



DSC00234



DSC00235



DSC00236



DSC00237



DSC00238



DSC00239



DSC00240



DSC00241



DSC00242



DSC00243



DSC00244