

Photo Album for
Cottage Grove FD., WI
Job # 37226
W/O # 30191085
March 25, 2023


Since the last report, the chassis began the paint process and the pump house finished with paint. The body began the paint process. Next week the chassis should continue with paint and the pump house may begin final pump assembly. The body should continue with paint.



DSC00611



DSC00612



DSC00613



DSC00614



DSC0615



DSC0616



DSC0617



DSC0618



DSC00858



DSC00859



DSC00860



DSC00861



<http://reliantfire.com/>



An Oshkosh Corporation Company