



# Photo Album for Sumner Fire Department, IA Job 38101 March 17, 2023

In this report your cab continued through paint while the body began fabrication. In the next report your cab may continue the paint process, and the body may continue fabrication.





DSC05142



DSC05143




DSC05144



DSC05145



DSC05146



DSC07116



DSC07117



DSC07118



DSC07119



DSC07120



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

