




# Photo Album for Sumner Fire Department, IA Job 38101 March 24, 2023

In this report your cab continued the paint process, the frame build began, and the body continued fabrication and was staged. In the next report your cab may continue through paint, the frame build may continue, and the body may complete fabrication and release to paint.




DSC04740



DSC04741



DSC04742



DSC04743





DSC04745



DSC00075



DSC00076



DSC00077





DSC00078



DSC00079



DSC00080



DSC00081





DSC07194



DSC07195



DSC07196



DSC07197





DSC07198

**Pierce**

DA Finish = Blue

Job Skid = Yellow

Job # **38101**

	Description	Job Color	Qty.	Clock #
1.	Access Panels (compartments)	Yellow	2	
2.	Air Bag Rack			

DSC07123



DSC07124



DSC07125



DSC07126



DSC07127



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2023 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956