Photo Album for Cottage Grove FD., WI Job # 37226 W/O # 30191085 March 4, 2023

Since the last report, the chassis was in staging (no photos) and the fire pump began to receive valves and plumbing. Next week the chassis should be in staging with the fire pump.



DSC00001



D000001



DSC00002



DSC00004







http://reliantfire.com/



An Oshkosh Corporation Company

