Photo Album for
Manchester Fire and Rescue IA

Job # 38007

W/O # 30614715

June 17, 2023

Since the last report, the chassis was in staging (no photos) and the pump house structure was joined with the fire pump. Next week the chassis should be in staging and the pump house may begin the paint process.





DSC00283



DSC00284





DSC00285 DSC00286







DSC00288





http://reliantfire.com/



An Oshkosh Corporation Company

