


Photo Album for Racine Fire Department, WI Job 37647-01 June 16, 2023

In this report your cab continued the paint process, the pump house completed initial assembly, and the body continued through paint. In the next report your cab may continue through paint, the pump house may remain staged, and the body may continue the paint process.



DSC04403



DSC04404



DSC04405



DSC04406



DSC04407



DSC01083



DSC01084




DSC01085



DSC01086



DSC01087



DSC04690



DSC04691



DSC04692



DSC04693



DSC04694



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

