


In-Production Photo Report for Hartford Fire and Rescue, WI Job# 37865

Status as of July 21, 2023

In this report the cab began initial assembly, the pump house continued initial assembly, and the body began the paint process. In the next report, the cab may continue initial assembly, the pump house may continue initial assembly, and the body may continue through paint.






DSC00178




DSC00179



DSC00180




DSC00105



DSC00106



DSC00107



DSC00108




DSC00109



DSC00110



DSC00111



DSC00589



DSC00590



DSC00591



DSC00592



DSC00593



<http://reliantfire.com/>



An Oshkosh Corporation Company