


# In-Production Photo Report for Hartford Fire and Rescue, WI Job# 37865

Status as of August 25, 2023

In this report your apparatus completed chassis assembly followed by the start of final assembly.  
In the next report final assembly may continue.





DSC00498




DSC00499



DSC00500



DSC00501



DSC00502



DSC00503



DSC00504



DSC00505



DSC00506



DSC00507



DSC00508



DSC00509



DSC00510



DSC00511



DSC00512



DSC00513



DSC00514



DSC00515



DSC00516



DSC00517



DSC00518




DSC00519



DSC00520



DSC00521



DSC00522



DSC00523



DSC00524



DSC00525



DSC00526



DSC00527



DSC00528



DSC00529



DSC00530



DSC00531



DSC00532



DSC00533



DSC00534



DSC00535



DSC00536



DSC00537



DSC00538



DSC00539



DSC00540



DSC00541



DSC00542



DSC00543



DSC00544



DSC00545



<http://reliantfire.com/>



An Oshkosh Corporation Company