


# In-Production Photo Report for City of Cedar Rapids Fire Department, IA Job# 37912

---

Status as of September 29, 2023

In this report your cab was staged to continue through paint, the pump house structure was staged, and the body completed fabrication. In the next report the cab may continue the paint process, the pump house structure may begin initial assembly, and the body may remain staged to begin in paint.





DSC03287



DSC03288



DSC03289




DSC03290





DSC03291



DSC00376



DSC00377



DSC00378



DSC03332



DSC03333



DSC03334





<https://reliantfire.com/>



An Oshkosh Corporation Company