


# In-Production Photo Report for City of Cedar Rapids Fire Department, IA Job# 37912

---

Status as of October 13, 2023

In this report your cab completed paint and was staged, the pump house began initial assembly, and the body began the paint process. In the next report the cab may remain staged to begin initial assembly, the pump house structure may continue initial assembly, and the body may continue through paint.






DSC00163



DSC00164



DSC00165




DSC00093






DSC00094



DSC00095



DSC00096



DSC00983





DSC00984



DSC00985



DSC00986



DSC00987



<https://reliantfire.com/>



An Oshkosh Corporation Company