


In-Production Photo Report for Lake Country Fire and Rescue, WI Job# 37991

Status as of October 06, 2023

In this report your cab completed fabrication and began the paint process while the forward body module began fabrication. In the next report your cab may continue through paint while the forward body module may complete the fabrication process.





DSC00818



DSC00819



DSC00820



DSC00092



DSC00093



DSC00094



<https://reliantfire.com/>



An Oshkosh Corporation Company