


In-Production Photo Report for Lake Country Fire and Rescue, WI Job# 37991

Status as of October 27, 2023

In this report your cab remained staged to continue the paint process, the forward body module completed paint then plumbing began installation, and the body began fabrication. In the next report your cab may begin the paint process, the forward body module may continue initial assembly, and the rear body module may complete fabrication.






DSC03470



DSC03471



DSC03472



DSC01344



DSC01345



DSC01346



DSC01347



DSC01348



DSC01349



DSC00011



DSC00012



DSC00013



DSC00014



DSC00015



<https://reliantfire.com/>



An Oshkosh Corporation Company