


In-Production Photo Report for City of Cedar Rapids Fire Department, IA Job# 37912

Status as of November 17, 2023


In this report your cab, pump house, and body were installed on the frame while chassis assembly continued. In the next report your apparatus may complete initial assembly followed by the start of final assembly.

Due to Pierce Thanksgiving Holiday break, your next report is scheduled for week ending December 02, 2023.





DSC00442



DSC00443



DSC00444



DSC00445



DSC00446



DSC00447



DSC00448



DSC00449



DSC00450



DSC00451



DSC00452



DSC00453



DSC00454



DSC00455



DSC00456



<https://reliantfire.com/>



An Oshkosh Corporation Company