Photo Album for Cross Plains FD., WI Job # 37792 W/O # 30536971 November 4, 2023

This week the chassis continued with chassis prep and the body began to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the body should continue with trim and wiring harnesses.



DSC00412



DSC00414




DSC00413



DSC00415







DSC00416



DSC00417



DSC00418 DSC00419





DSC00420



DSC00440



DSC00442



Find us on Facebook



DSC00443





http://reliantfire.com/



An Oshkosh Corporation Company

