


In-Production Photo Report for Kilbourn Volunteer Fire Department, WI Job# 38102

Status as of November 17, 2023

In this report the apparatus continued test while the aerial device continued assembly. In the next report the aerial device may be pinned to the apparatus followed by the start of aerial testing.

Due to Pierce Thanksgiving Holiday break, your next report is scheduled for week ending December 02, 2023.





DSC00782



DSC00783



DSC00784



DSC00785



DSC00786



DSC00787



DSC00788



DSC00789



DSC00790




DSC00791



DSC00792



DSC00793



DSC00794



DSC00795



DSC00796



DSC00797




DSC00798



DSC00799



DSC00800



DSC01170



DSC01171



DSC01172



DSC01173



DSC01174



DSC01175



DSC01176



DSC01177



DSC01178



DSC01179



<https://reliantfire.com/>



An Oshkosh Corporation Company