


# In-Production Photo Report for Mount Pleasant Fire Department, IA Job# 40167

---

Status as of January 12, 2024

In this report your cab completed paint and was staged, the frame build began, the front body module was fabricated, and the rear body module completed fabrication and was staged. In the next report your cab may remain staged to begin initial assembly, the frame build may continue, the front body module may begin the paint process, and the rear body module may remain staged to begin the paint process.





DSC03253



DSC03254



DSC03255



DSC03256



DSC00379



DSC00380



DSC00381



DSC00382



DSC00383



DSC00528



DSC00529



DSC00530



DSC03345



DSC03346



DSC03347



DSC03348



<https://reliantfire.com/>



An Oshkosh Corporation Company